

HABS
SC
10-CHAR
54-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

South Carolina Railroad-Southern Railway Co.
William Aiken House
456 King Street
Charleston
Charleston County
South Carolina

HABS No. SC-373 A

Louis Schwartz, Photographer April, 1969

- SC-373 A-1 EXTERIOR, WEST FRONT AND SOUTH SIDE
- SC-373 A-2 EXTERIOR EAST REAR AND SOUTH SIDE
- SC-373 A-3 EXTERIOR, EAST REAR AND NORTH SIDE
- SC-373 A-4 EXTERIOR, WEST SIDE
- SC-373 A-5 INTERIOR, FIRST FLOOR, ENTRANCE HALL
- SC-373 A-6 INTERIOR, SECOND FLOOR, DRAWING ROOM, NORTHWEST CORNER
- SC-373 A-7 INTERIOR, EAST SIDE, SECOND FLOOR

ADDENDUM
10-11-69

HABS
SC,
10-CHAR,
54-

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

Addendum to:

South Carolina Railroad-Southern Railway Company
William Aiken House
456 King Street
Charleston
Charleston County
South Carolina

HABS No. SC-373 A

Photos SC-373 A-1 thru SC-373 A-7 were previously transmitted to the Library of Congress.

The photos below were taken for the 1977-79 South Carolina project made possible by grants from the National Endowment for the Arts. Charles N. Bayless, AIA, was the photographer.

EXTERIOR PHOTOS taken September 1978

INTERIOR PHOTOS taken January 1979

- | | |
|-------------|--|
| SC-373 A-8 | WEST FRONT (left) AND SOUTH SIDE, FROM SOUTHWEST |
| SC-373 A-9 | NORTH SIDE |
| SC-373 A-10 | EAST SIDE (rear) |
| SC-373 A-11 | SOUTH SIDE, SHOWING TWO-STORY PORCHES |
| SC-373 A-12 | WEST SIDE, FIRST FLOOR PORCH |
| SC-373 A-13 | SOUTHWEST CORNER, SECOND FLOOR PORCH |
| SC-373 A-14 | WEST SIDE, GROUND FLOOR ENTRY |
| SC-373 A-15 | SOUTH SIDE, FIRST FLOOR PORCH: MAIN ENTRY. Note jib doors under windows. |
| SC-373 A-16 | GROUND FLOOR, STAIRHALL |
| SC-373 A-17 | GROUND FLOOR: HALL CEILING |
| SC-373 A-18 | FIRST FLOOR, STAIRHALL: SOUTH ENTRY TO FIRST FLOOR PORCH
(see also SC-373 A-15) |

(continued on page 2)

SOUTH CAROLINA RAILROAD-SOUTHERN RAILWAY COMPANY
WILLIAM AIKEN HOUSE
Index To Photographs
HABS No. SC-373 A (page 2)

SC-373 A-19 FIRST FLOOR: HALL CEILING

SC-373 A-20 FIRST FLOOR, WEST ROOM, NORTH WALL

SC-373 A-21 FIRST FLOOR, WEST ROOM, EAST AND SOUTH WALLS: LOOKING INTO HALL

SC-373 A-22 FIRST FLOOR, WEST ROOM, EAST WALL: FALSE DOOR.
Real door in this room has same design

SC-373 A-23 FIRST FLOOR, WEST ROOM, NORTH WALL: CHIMNEYPiece AND MANTLE

SC-373 A-24 FIRST FLOOR, WEST ROOM: CORNICE DETAIL

SC-373 A-25 FIRST FLOOR, WEST ROOM: CEILING CENTERPIECE

SC-373 A-26 FIRST FLOOR, BALLROOM, LOOKING SOUTHEAST

SC-373 A-27 FIRST FLOOR, BALLROOM: TYPICAL WINDOW

SC-373 A-28 FIRST FLOOR, BALLROOM: CORNICE AND WINDOW ARCHITRAVE DETAIL.
Door architrave similar.

SC-373 A-29 FIRST FLOOR, BALLROOM: CEILING CENTERPIECE

SC-373 A-30 SECOND FLOOR: HALL CEILING

SC-373 A-31 DISCARDED ORIGINAL MANTLE (location not ascertained)